



"ACT now...to solve your repair requirements".

V2500-A1/A5 Thrust Reverser



ACT can support your **V2500-A1/A5 Thrust Reverser (PN:740-0002-Series & 745-0002-Series)** Repair/Overhaul requirements with our extensive composite experience. We will evaluate your units for repair & can offer you exchange units, if the repair requires a long turn-time.

ACT has a set of V2500-A1 RH/LH Thrust Reversers available for advance exchange, in support of your aircraft requirement.

Contact our Sales Department for any of your Nacelle & Reverser requirements at (305) 888-5844 and ask for Alex or Rudolf.

Aircraft Composite Technologies, Inc.

7860 N.W. 76th Avenue
Miami, FL 33166
Phone: 305.888-5844
Fax: 305.888.3584

Website:
www.aircraftcomposite.com

FAA Repair Station No.
ICNR513X

